



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	10,572.3	TSO:	0.0	W/O#:	6985
PCE:	93030	CSN:	12,230	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041501	98A238	5,364	24,636
Disk, 2 nd Stg.	3023112	A2989	9,616	10,384
Disk, 3 rd Stg.	3023113	B0661	9,616	10,384
Impeller	3017463	9A877	12,230	7,770
Disk, CT	3049291-01	A000MK9C	3,714	6,286
PT Disk, 1 st Stg.	3029312	5W632	8,424	21,576
PT Disk, 2 nd Stg.	3029313	TBA	7,535	22,465
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024-01	1746573	0.0
FUEL PUMP	025323-300-03	6655	0.0
FUEL CONTROL UNIT	3244768-13	A69188	0.0
OIL/FUEL HEATER	10585K-G-H-J	635	0.0
COMP. BLEED VALVE	3100922-05	9F630	0.0
COMP. BLEED VALVE	3100923-03	2F200	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: Post SB 3360
 All engines ship FOB ATS dock.