



**Airforce Turbine Service**  
**www.PT6A.aero**

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| <b>Engine Rotor Sheet</b> |              |      |                |      |            |       |             |
|---------------------------|--------------|------|----------------|------|------------|-------|-------------|
| PT6A:                     | <b>-42</b>   | TSN: | <b>8,696.5</b> | TSO: | <b>0.0</b> | W/O#: | <b>6921</b> |
| PCE:                      | <b>94620</b> | CSN: | <b>9,338</b>   | CSO: | <b>0.0</b> | TSHS: | <b>0.0</b>  |

| <b>Life Limited Part (LLP) Listing</b>          |            |          |          |           |
|-------------------------------------------------|------------|----------|----------|-----------|
|                                                 | P/N        | S/N      | Cycles   |           |
|                                                 |            |          | Consumed | Remaining |
| Hub, 1 <sup>st</sup> Stg.                       | 3040501    | 57A737   | 9,338    | 20,662    |
| Disk, 2 <sup>nd</sup> Stg.                      | 3023112    | 66A952   | 9,338    | 10,662    |
| Disk, 3 <sup>rd</sup> Stg.                      | 3023113    | 68A030   | 9,338    | 10,662    |
| Impeller                                        | 3036793    | 6E924    | 9,338    | 10,662    |
| Disk, CT                                        | 3049291-01 | A001480K | 3,221    | 6,779     |
| PT Disk, 1 <sup>st</sup> Stg.                   | 3029312    | 66A283   | 9,338    | 20,662    |
| PT Disk, 2 <sup>nd</sup> Stg.                   | 3029313    | 63A622   | 9,338    | 20,662    |
| Key: TBA = To be assigned, N/A = Not Applicable |            |          |          |           |

| <b>Accessories</b>                              |             |         |     |
|-------------------------------------------------|-------------|---------|-----|
|                                                 | P/N         | S/N     | TSO |
| PROPELLER GOVERNOR                              | 8210-024-01 | 1818633 | 0.0 |
| FUEL PUMP                                       | 025323-300  | 10149   | 0.0 |
| FUEL CONTROL UNIT                               | 3244768-13  | B12756  | 0.0 |
| OIL/FUEL HEATER                                 | 10585J      | WA2599  | 0.0 |
| COMP. BLEED VALVE                               | 3100922-05  | 4K389   | 0.0 |
| COMP. BLEED VALVE                               | 3100923-02  | 3K056   | 0.0 |
| Key: TBA = To be assigned, N/A = Not Applicable |             |         |     |

Comments: Post SB 3360  
 All engines ship FOB ATS dock.