



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	16,469.9	TSO:	3,667.8	W/O#:	9088
PCE:	50385	CSN:	20,995	CSO:	5,916	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	82A069	16,714	2,286
Disk, 2 nd Stg.	3013712	7243	21,045	2,955
Disk, 3 rd Stg.	3011713	6855	21,045	3,955
Impeller	3013176	9C462	16,034	2,966
Disk, CT	3013411	A002DM67	15,576	424
PT Disk, 1 st Stg.	3022412	A2603	12,552	7,448
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2173961	270.3
FUEL PUMP	025323-101-02	4088	3,667.8
FUEL CONTROL UNIT	2524440-9-6-8	A66785	2,689.8
START FLOW CONTROL	3019109	12816	3,667.8
OIL/FUEL HEATER	10552E	384	3,667.8
COMP. BLEED VALVE	3100829-03	1A374	1,494.9
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.