



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	12,127.40	TSO:	0.0	W/O#:	TBA
PCE:	PG0248	CSN:	12,898	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1B102	6,334	12,666
Disk, 2 nd Stg.	3013712	9R070	15,461	8,539
Disk, 3 rd Stg.	3011713	8A993	10,706	14,294
Impeller	3013176	2A786	8,665	10,335
Disk, CT	3013411	73A902	8,494	7,506
PT Disk, 1 st Stg.	3022412	7R712	12,829	7,171

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-03	TBA	0.0
FUEL CONTROL UNIT	3244745-3	TBA	0.0
START FLOW CONTROL	30366402	TBA	0.0
OIL/FUEL HEATER	10552E	TBA	0.0
COMP. BLEED VALVE	3100829-03	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.