



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	10,451	TSO:	3,485.0	W/O#:	9409
PCE:	52151	CSN:	12,060	CSO:	4,889	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9C931	12,060	6,940
Disk, 2 nd Stg.	3013712	7D533	12,060	11,940
Disk, 3 rd Stg.	3011713	6C296	12,060	12,940
Impeller	3013176	7A461	12,060	6,940
Disk, CT	3013411	A00004N2	15,399	601
PT Disk, 1 st Stg.	3022412	7C695	12,060	7,940
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	983056	269.2
FUEL PUMP	025323-101-02	7979	3,485.0
FUEL CONTROL UNIT	252444-0-7-6	A25113	1,741.7
START FLOW CONTROL	3019109	13301	3,485.0
OIL/FUEL HEATER	10552E	1129	3,485.0
COMP. BLEED VALVE	3100829-03	8F793	3,485.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.