



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	11,433.7	TSO:	567.1	W/O#:	9168
PCE:	17405	CSN:	13,003	CSO:	910	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1Y637	13,003	5,997
Disk, 2 nd Stg.	3013712	1A890	18,660	5,340
Disk, 3 rd Stg.	3011713	6487	19,815	5,185
Impeller	3027798	7E420	14,644	4,356
Disk, CT	3013411	A00004N2	15,399	601
PT Disk, 1 st Stg.	3026812	23B801	18,275	1,725
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2476713	567.1
FUEL PUMP	702801-5	0249	567.1
FUEL CONTROL UNIT	3244809-8	C25593	2,294.1 (TSN)
FLOW DIVIDER	3019906/25536-4	12855	567.1
OIL/FUEL HEATER	10552E	1276	567.1
COMP. BLEED VALVE	3049038-03	GA1151	567.1
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.