



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65AR	TSN:	GG: 6,806.7 PS: 7,120.4	TSO:	0.0	W/O#:	6568
PCE:	97474	CSN:	GG: 5,970 PS: 6,460	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3037101	64B798	453	23,547
Shaft Comp. Rotor	3037277	16A961	5,970	9,030
Disk, 2 nd Stg.	3036802	4X293	16,913	7,087
Disk, 3 rd Stg.	3036803	11A427	16,139	7,861
Disk 4 th Stg.	3036804	14A058	16,139	7,861
Impeller	3036794	5D352	5,970	18,030
Disk, CT	3040311	19A464	5,970	9,030
PT Disk, 1 st Stg.	3029312	8Y640	6,460	23,540
PT Disk, 2 nd Stg.	3029313	15A386	6,460	23,540
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-034	2169973G	0.0
FUEL PUMP	30338086	2101	0.0
FUEL CONTROL UNIT	8061-329	1998638	0.0
OIL/FUEL HEATER	10585H	5025	0.0
COMP. BLEED VALVE	3123126-01	310932	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.