



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	GG: 6,670.4 PS: 9,046.7	TSO:	GG: 1,919.4 PS: 416.7	W/O#:	8322
PCE:	GG: 51990 PS: 51005-100	CSN:	GG: 5,017 PS: 8,259	CSO:	GG: 1,595 PS: 358	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	06B777	5,017	13,983
Disk, 2 nd Stg.	3013712	09B672	5,017	18,983
Disk, 3 rd Stg.	3011713	09B520	5,017	19,983
Impeller	3013176	05A595	5,017	13,983
Disk, CT	3013411	08B984	5,017	10,983
PT Disk, 1 st Stg.	3026812	9D879	8,827	11,173
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1704533	416.7
FUEL PUMP	025323-101-03	7072D	422.9
FUEL CONTROL UNIT	2524440-9	C7179	422.9
START FLOW CONTROL	3019109	11939	422.9
OIL/FUEL HEATER	10552E	2918	422.9
COMP. BLEED VALVE	3100829-03	3A449	422.9
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.