



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	GG: 8,630.0 PS: 9,046.7	TSO:	GG: 0.0 PS: 416.7	W/O#:	6913
PCE:	51005	CSN:	GG: 7,901 PS: 8,259	CSO:	GG: 0.0 PS: 358	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	4E573	5,595	13,405
Disk, 2 nd Stg.	3013712	A0692	10,194	13,806
Disk, 3 rd Stg.	3011713	4E449	14,701	10,299
Impeller	3013176	2H712	5,996	13,004
Disk, CT	3013411	8Y429	9,662	6,338
PT Disk, 1 st Stg.	3026812	9D879	8,827	11,173
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1704533	416.7
FUEL PUMP	025323-101	9825	0.0
FUEL CONTROL UNIT	2524440-7-6	A74303	0.0
START FLOW CONTROL	3019109	TBA	0.0
OIL/FUEL HEATER	10552E	4846	0.0
COMP. BLEED VALVE	3100829-03	6C739	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.